Clipping Stand Assembly Instructions

Step 1: Lay the clipping stand upside down on its back with the leg support arms facing up. Place the leg support piece in the grooves of the leg support arms with the two tabs welded on the cross bar facing up.



Step 2: Insert a 3/8" x 2 ½" bolt through the leg support piece and the tabs welded to the clipping stand frame. Use 3/8" washers on the nut side. Follow this step for both the front and back leg supports.



Step 3: Insert the square 18" long 3/4" sq leg brace support tubing into the tabs welded on the crossbar of the leg support piece. Use a 3/8" x 2" bolt to attach. Use a 3/8" washer on the nut side. Follow this step for both the front and back leg supports.



Step 4: Insert the 3/8" x 3" (larger) lynch pin through the tabs and the 3/4" square leg brace support tubing. Follow this step for both the front and back leg supports.



Step 5: Insert the four adjustable legs into the leg support arms using the 3/8" x 2" (smaller) lynch pin to attach at the desired height.



Step 6: With the clipping stand still up side down, screw two black knob bolts into the square tube welded on the front bottom side of the main deck. These will adjust the head piece front to back on the main deck.

Show Stopper Equipment
by Vittetoe, Inc.
Keota, Iowa 800-848-8386 www.vittetoe.com

Step 7: Turn the clipping stand over so the legs are on the floor and the stand is sitting upright.

Take the "L" square tube headpiece mounting bracket and screw two black knob bolts into it. These two knobs will adjust the height of the headpiece.



<u>Step 8:</u> Facing the front of the stand, insert the "L" headpiece mounting bracket into the square tube welded to the main deck. Tighten black knobs under main deck to desired location.



Insert headpiece into top of "L" headpiece mounting bracket. Tighten 2 black knobs on front of bracket to desired height of headpiece.

Step 9: Insert side rails in holes on sides of clipping stand.



Step 10: To tear down, remove the side rails and head piece. Turn the clipping stand on its side and remove the two 3/8" x 3" lynch pin. Push the leg support brackets against the clipping stand. Push the ³/₄" square tube leg support braces into the tabs and use the 3/8" x 3" lynch pins to lock into place.



